

	Typ	L #	Hits	S arch Text	DB
1	IS&R	L2	1	("5857247").PN.	US- P PUB; USPAT
2	BRS	L3	78454	(squib or buckle or connector or latch) near6 (fire or firing or fired or unlatch or unlatching or unlatched or disconnect or disconnecting or disconnected or unbuckle or release or releasing or released)	US- PGPUB; USPAT; EPO; JPO; DERWE NT
3	BRS	L4	62690	water with (activating or activate or activated)	US- PGPUB; USPAT; EPO; JPO; DERWE NT
4	BRS	L5	77	3 same 4	US- PGPUB; USPAT; EPO; JPO; DERWE NT
5	BRS	L6	17	5 and parachute	US- PGPUB; USPAT; EPO; JPO; DERWE NT

	Time Stamp	C mments	Error Definition	Errors
1	2005/01/20 18:24			
2	2005/01/20 18:30			
3	2005/01/20 18:31			
4	2005/01/20 18:31			
5	2005/01/20 18:47			

	Type	L #	Hits	Search Text	DB
6	BRS	L7	40518	battery and (probe or sensor or wire) and (capacitor or capacitance or capacitive)	US-P PUB; USPAT; EPO; JPO; DERWE NT
7	BRS	L8	3	6 and 7	US-PGPUB; USPAT; EPO; JPO; DERWE NT
8	BRS	L9	1	8 and diode	US-PGPUB; USPAT; EPO; JPO; DERWE NT
9	IS&R	L10	3904	((340/618) or (340/620) or (340/604) or (340/573.1) or (73/290R)).CCLS.	US-PGPUB; USPAT
10	BRS	L11	6	10 and 3 and 4	US-PGPUB; USPAT; EPO; JPO; DERWE NT
11	IS&R	L12	375	(340/644).CCLS.	US-PGPUB; USPAT

	Tim Stamp	Comm nts	Error D finiti n	Erro rs
6	2005/01/20 18:42			
7	2005/01/20 19:44			
8	2005/01/20 18:43			
9	2005/01/20 18:47			
10	2005/01/20 19:44			
11	2005/01/20 19:55			

	Type	L #	Hit	Search Text	DBs
12	BRS	L13	0	12 and 5	US- P PUB; USPAT; EPO; JPO; DERWE NT
13	BRS	L14	0	12 and 5	US- PGPUB; USPAT; EPO; JPO; DERWE NT
14	BRS	L15	240	244/151B	US- PGPUB; USPAT; EPO; JPO; DERWE NT
15	IS&R	L16	117	(244/151B).CCLS.	US- PGPUB; USPAT
16	BRS	L17	3	16 and 5	US- PGPUB; USPAT; EPO; JPO; DERWE NT

	Tim Stamp	Comm nt	Error Definiti n	Errors
12	2005/01/20 19:55			
13	2005/01/20 19:55			
14	2005/01/20 20:02			
15	2005/01/20 20:02			
16	2005/01/20 20:07			